



FIGURE 1

SIDE VIEW OF WIDE SHOE PRESS

Figure 2: Relationship Between Peak Pressure and Line Load



120 MM SHOE---90KN/M (TYPICAL;SHOE PRE\$S) 80 NEW SHOE DESIGN 50 MM SHOE---90 KN/ 9 20 NIP POSITION, MM NIP PRESSURE PROFILE PRESSURE ROLL BO KN/M FIGURE 3 5000 3000 4000 2000 1000 NIP LOAD, KN/SQUARE METER








FIG. 5 -- CONVENTIONAL THROUGH-AIR-DRYING PROCESS LAYOUT









TOHITT SHEZSSED FIGURE 8





FIGURE 9

SHOE PRESS WITH LARGE DIAMETER TRANSFER CYLINDER AND WITH FELT PARTIALLY WRAPING CYLINDER



The state of the s

FIGURE 10






FIGURE 11

SHOE PRESS TAPERED ON THE EXIT SIDE SO THAT FELT CAN BE RAPIDLY REMOVED FROM THE SHEET WHILE THE BLANKET IS SIMULTANEOUSLY RAPIDLY REMOVED FROM THE FELT








FIG. 13




FIG. 14




FIG. 15